


## EtherCAT Connector Part Number Key

### M12x1 Pre-moulding Connector




- 1 E M12x1 Connector
- 2 I EtherCAT
- 3 L Right Angle  
Blank Straight

- 4 K Female  
Z Male
- 5 Number of Pins  
Contact Distribution

- 6 Length [m]
- 7 Cable Jacket  
F230/F211/F231  
F21/F23

### RJ45 Pre-moulding Connector



- 1 T Right angle, Buckle up  
B Right angle, Buckle down
- 2 RJ45 EtherCAT
- 3 S Shielded  
Blank Unshielded

- 4 Length [m]
- 5 Cable Jacket  
F230/F211/F231  
F21/F23